

|   |  |   |   |
|---|--|---|---|
| AMENDMENT OF SOLICITATION/MODIFICATION OF CONTRACT  |  | 1. CONTRACT ID CODE                                   | PAGE OF PAGES<br>1-5                                |
| 2. AMENDMENT/MODIFICATION NO.<br><br>A001   | 3. EFFECTIVE DATE<br><br>August 13, 2020   | 4. REQUISITION/PURCHASE REQ. NO.<br><br>PR9108001     | 5. PROJECT NO. (If applicable)<br>19PK400-20-Q-5044 |
| 6. ISSUED BY<br><br>CODE<br><br>Contracting Officer<br>Department of State<br>U.S. Consulate General<br>Karachi.  |  | 7. ADMINISTERED BY (If other than Item 6)<br><br>CODE |   |
| 8. NAME AND ADDRESS OF CONTRACTOR (NO., street,city,county,State,and ZIP Code)<br><br>Offerors  |  | 9a. AMENDMENT OF SOLICITATION<br>PR9108001            |   |
|   |  | 9b. DATED (SEE ITEM 11)<br><br>August 13, 2020        |   |
|   |  | 10a. MODIFICATION OF CONTRACT/ORDER NO.<br><br>001    |   |
|   |  | 10b. DATED (SEE ITEM 13)                              |   |
| <b>11. THIS ITEM ONLY APPLIES TO AMENDMENTS OF SOLICITATIONS</b>  |  |   |   |
| <p><input type="checkbox"/> The above numbered solicitation is amended as set forth in Item 14. The hour and date specified for receipt of Offers <input type="checkbox"/> is extended, <input checked="" type="checkbox"/> is not extended</p> <p>Offers must acknowledge receipt of this amendment prior to the hour and date specified in the solicitation or as amended, by one of the following methods: (a) By completing Items 8 and 15, and returning <u>01</u> copies of the amendment;(b) By acknowledging receipt of this amendment on each copy of the offer submitted; or(c) By separate letter or telegram which includes a reference to the solicitation and amendment numbers.</p> <p><b>FAILURE OF YOUR ACKNOWLEDGMENT TO BE RECEIVED AT THE PLACE DESIGNATED FOR THE RECEIPT OF OFFERS PRIOR TO THE HOUR AND DATE SPECIFIED MAY RESULT IN REJECTION OF YOUR OFFER.</b> If by virtue of this amendment you desire to change an offer already submitted, such change may be made by telegram or letter, provided each telegram or letter makes reference to the solicitation and this amendment and is received prior to the opening hour and date specified.</p> |  |   |   |
| 12. ACCOUNTING AND APPROPRIATION DATA (If required)   |  |   |   |
| <b>13. THIS ITEM APPLIES ONLY TO MODIFICATIONS OF CONTRACTS/ORDERS, IT MODIFIES THE CONTRACT/ORDER NO. AS DESCRIBED IN ITEM 14.</b>   |  |   |   |
|   | A. THIS CHANGE ORDER IS ISSUED PURSUANT TO: (Specify authority) THE CHANGES SET FORTH IN ITEM 14 ARE MADE IN THE CONTRACT ORDER NO. IN ITEM 10A.   |   |   |
|   | B. THE ABOVE NUMBERED CONTRACT/ORDER IS MODIFIED TO REFLECT THE ADMINISTRATIVE CHANGES (such as changes in paying office, appropriation date, etc.) SET FORTH IN ITEM 14, PURSUANT TO THE AUTHORITY OF FAR 43.103(b) |   |   |
|   | C. THIS SUPPLEMENTAL AGREEMENT IS ENTERED INTO PURSUANT TO AUTHORITY OF:   |   |   |
| X   | D. OTHER (Specify type of modification and authority)  |   |   |
| E. IMPORTANT: Contractor <input checked="" type="checkbox"/> is not, <input type="checkbox"/> is required to sign this document and return <u>01</u> copies to the issuing office.  |  |   |   |

**14. DESCRIPTION OF AMENDMENT/MODIFICATION** (Organized by UCF section headings, including solicitation/contract subject matter where feasible.)

The purpose of this amendment is as follow,

- 1- To amend contractor pre-proposal site conference participant protocol - Two (2) participants per organization permitted.
- 2- To amend Statement of Work details of paintwork – edits added from Page 3 of this document.

Except as provided herein, all terms and conditions of the document referenced in SOW, as heretofore changed, remains unchanged and in full force and effect.

|  |                  |   |                  |
|--|------------------|---|------------------|
| 15A. NAME AND TITLE OF SIGNER (Type or print)        |                  | 16A. NAME OF CONTRACTING OFFICER  |                  |
|  |                  | Sandra A Castillo   |                  |
| 15B. NAME OF CONTRACTOR/OFFEROR                      | 15C. DATE SIGNED | 16B. UNITED STATES OF AMERICA   | 16C. DATE SIGNED |
| BY _____<br>(Signature of person authorized to sign) |                  | BY <br>(Signature of Contracting Officer) | 8/13/2020        |

NSN 7540-01-152-8070  
Previous edition unusable

Standard Form 30 (revised 10/83)  
Prescribed by GSA FAR (48 CFR) 53.243

| ITEM #    | DESCRIPTION   | UNIT | Quantity |
|-----------|---|------|----------|
| <b>01</b> | <b>Barriers and Access Control</b>  |      |          |
|           | Frere compound Plot #2 perimeter barrier (wall) does not meet 9 ft. (2.75 meter) height requirement. In addition, several external tall (6ft) concrete planters are placed very close to the perimeter walls, consequently providing a climbable platform to surmount the compound wall.  | SFT  | 1500     |
| a)        | Contractor shall install host nation-approved anti-climb topping to achieve minimum overall perimeter wall height of 9 ft. (2.75 m). Anti-climb topping should be double concertina similar to New Consular Compound (NCC) Karachi.   | RFT  | 1700     |
| b)        | Contractor shall trim overhanging branches, limbs, wires, cables, along the perimeter wall of Plot #2, which could be used for hand or footholds to scale the wall from the exterior.   | Job  | 1        |
| c)        | Contractor shall install rows of razor teeth or similar robust, low-profile anti-climb measure on lower doorway or patio roof edges of residences as needed.  | Job  | 1        |
| d)        | Contractor shall relocate tall concrete planters located at the far end of Mehta Drive and far end of Golf Drive, next to the wall, and move them off the wall to abutting concrete curbs or create distance from wall of at least three feet. Where the external planters cannot be relocated, affix concertina or razor spikes to top edges to deter/deny access. | EA   | 50       |

|           |  |      |   |
|-----------|--|------|---|
|           |  |      |   |
| <b>02</b> | <b>Perimeter Walls &amp; Gates</b>   |      |   |
|           | Gates are outdated, corroded/rusted, have noticeable gaps, and the masonry pillar connecting them is deteriorating. Also, there is a pedestrian gate that is not needed or impractical for egress usage, and any gap within a perimeter at all presents a weak point within the outer-ring of security.  |      |   |
| a)        | Contractor shall replace existing legacy gates with 9 ft. (2.75 m) robust metal gates w/anti-climb topping; to include improvement of masonry pillars to support new gates while raising pillar height to meet minimum wall requirement of 9ft (2.75m).  | EA   | 2 |
| b)        | Contractor shall remove pedestrian gate located between Golf 2 and Golf 3, and in-fill with grout-filled, reinforced concrete masonry units or similar masonry construction to existing wall to meet 9 ft. (2.75m) perimeter wall height requirement.  | EA   | 1 |
| c)        | Apply two coats of primer (red oxide) and two coats of epoxy or oil based paint on newly installed gates.  | EA   | 3 |
|           |  |      |   |
| <b>03</b> | <b>Residential Door Improvements</b>   |      |   |
|           | Several exterior doors do not meet current security standards, and a few safe haven doors need additional reinforcement.   |      |   |
| a)        | Contractor shall install additional metal plates to the outside face of any interior door that leads to the safe haven that has an overhead glass panel that is not reinforced on both sides with metal plates, i.e., one side is metal and the other side is glass or wood with glass; both sides need to be hardened and reinforced with metal to ensure full compliance. (Golf 3 Upper Unit and Golf 3 Lower Unit). | Nos. | 8 |
| b)        | Contractor shall replace the exterior door to Golf 3 Lower Unit (Main Exterior Entrance Door) with a substantial metal, solid wood, or wood/metal hybrid doorframe as found on most residential entrances.   | Nos  | 7 |
| c)        | Contractor shall replace the Golf 2 door on the upstairs floor that leads to the fire escape stairway with a substantial metal, solid wood,  | Nos  | 1 |

|           |   |     |    |
|-----------|---|-----|----|
|           | or wood/metal hybrid doorframe as found on most residential entrances.  |     |    |
| d)        | Contractor shall install additional 1/8" metal or armored metal plate to Golf 2 upper stairway (Safe Haven) grilled door or if feasible replace existing door with 2" tubular frame and 1/4" steel plates on front and back surface to approximate 15-minute FEBR protection. | Nos | 1  |
| e)        | Contractor shall replace the exterior doors to Metha 3 Lower Unit of both the Main Exterior Entrance Door and the Back Exterior Door (3MD D2) with substantial metal, solid wood, or wood/metal hybrid doorframe as found on most residential entrances.                      | Nos | 2  |
| f)        | Contractor shall replace all locks to each Main Entrance Door residence with Yale jimmy-proof deadlock or cipher lock; plunger dead bolts, Sargent & Greenleaf SM-181 dead bolts or similar mechanism to increase forced entry resistance.                                    | Nos | 2  |
| g)        | Contractor shall paint two coats of primer (red oxide) and two coats of epoxy or oil-based paint on all reinforced and replaced doors.  | Nos | 19 |
|           |   |     |    |
| <b>04</b> | <b>Residential Window Grille Improvements</b>   |     |    |
|           | Each window that does not have a grille needs to have one installed.  | Qty | 36 |
| a)        | Contractor shall install window grilles to 3-Metha Upper level residence, Bevelle Extension windows located in the hallway, and Bevelle Upper level residential windows.  |     |    |
| b)        | Contractor shall replace any protruding window grille cages with ones that mount flat to wall surface.  |     |    |
| c)        | Contractor shall weld heavy gauge wire mesh to all exterior grille faces to deny their use as hand/foot holds and mitigate against penetration of incendiary devices, e.g., Molotov cocktails.  |     |    |
| d)        | Contractor shall apply two coats of primer (red oxide) and two coats of epoxy or oil-based paint on new window grills.  |     | 36 |

|           |  |     |   |
|-----------|--|-----|---|
|           |  |     |   |
| <b>05</b> | <b>External Fire Escapes</b>   |     |   |
|           | External fire escape staircases do not have access control or gate/cage to prevent access to upper level windows, doors or rooftops.   |     |   |
| a)        | Contractor shall install metal mesh cage with internal lock release on each residence that has a fire escape lower staircase. Mesh frame needs to be painted with two coats of primer and two coats of epoxy or oil-based paint. | Nos | 5 |
| b)        | Residences include: Mehta 3, Mehta 1, Bevelle Down, Golf 3, and the American Club.   |     |   |